


# ROCK SOCK – MODULAR STORMWATER FILTER



8" DIAMETER (6" EFFECTIVE HEIGHT). 36" LENGTH, 55 LBS PER PIECE, 40 PIECES PER SHIPPING PALLET.

SHIPPING PALLET IS 2300 LBS.

NETTING IS HIGH STRENGTH POLYESTER (HIGH FLOW, UV-RESISTANT, MULTI-FILAMENT KNIT TEXTILE.

COLOR IS HI-VISIBILITY ORANGE OR GREEN.

FILL IS A 50-50 BLEND OF 1½ (MINUS) DUST-FREE LIMESTONE GRAVEL AND COMPOSTED HARDWOOD CHIP.

6" PIG TAILS ADDED FOR EASE OF HANDLING.

DOUBLE HOG RING CLOSURE PREVENTS OPENING.

## ROCK SOCK MAINTENANCE NOTES:

1. INSPECT BMPS EACH WORKDAY, AND MAINTAIN THEM IN EFFECTIVE OPERATING CONDITION. MAINTENANCE OF BMPS SHOULD BE PROACTIVE, AND NOT REACTIVE.

2. FREQUENT OBSERVATIONS AND MAINTENANCE ARE NECESSARY TO MAINTAIN BMPS IN EFFECTIVE OPERATING CONDITION. INSPECTIONS AND CORRECTIVE MEASURES SHOULD BE DOCUMENTED THOROUGHLY.

3. WHERE BMPS HAVE FAILED, REPAIR OR REPLACEMENT SHOULD BE INITIATED UPON DISCOVERY OF THE FAILURE.

4. ROCK SOCKS SHALL BE REPLACED IF THEY BECOME HEAVILY SOILED, OR DAMAGED BEYOND REPAIR.

5. SEDIMENT ACCUMULATED UPSTREAM OF THE ROCK SOCKS SHALL BE REMOVED AS NEEDED TO MAINTAIN FUNCTIONALITY OF THE BMP (TYPICALLY WHEN DEPTH OF ACCUMULATED SEDIMENT IS APPROXIMATELY ½ OF THE EFFECTIVE HEIGHT OF THE ROCK SOCK CONFIGURATION).

6. ROCK SOCKS ARE TO REMAIN IN PLACE UNTIL THE UPSTREAM DISTURBED AREA IS STABILIZED AND APPROVED BY THE LOCAL JURISDICTION.

7. WHEN ROCK SOCKS ARE REMOVED, ALL DISTURBED AREAS SHALL BE COVERED WITH TOPSOIL, SEEDED AND MULCHED OR OTHERWISE STABILIZED AS APPROVED BY THE LOCAL JURISDICTION.

CALL MFG (MKB COMPANY – 888-578-0777) TO FIND DISTRIBUTOR NEAR YOU.

## EXAMPLE CONFIGURATIONS:

